Energy at Shirley Heath School







Energy Audit Identified – LED replacement

- Energy Audit identified lots of old bulbs like T8 and T12's should be considered for replacement with LED's
- Audit suggested that priority to be give to external lights
- Rooms with high ceilings such as halls (which will also save on maintenance cost as to change them you need a platform)

Result & Action

The school replaced the main hall, and dining area, and 5 classrooms with LED lights





Energy Audit Identified – LED replacement Hall








Energy Audit Identified – LED replacement Dining Room






before




Energy Audit Identified – LED replacement classroom





Energy Audit Identified - Draughts



Doors being left open





£169 each

Result & Action

Site installed **plastic curtains** into two classrooms.



Energy Audit – Future Plans



Energy Audit Identified – LED & Uninsulated Pipework

- Replacing external / car park lights with LED
- There are a few issues of uninsulated pipework in the school, which contribute heat to the room, sometimes welcomed, but generally it will not be as it's not controllable.
- The cost to insulate these pipes is low to medium and gives quite good payback, but more importantly stops this uncontrolled heat and helps prevent discomfort.

Future plans

- Change outside lighting to LED
- Insulate Heating pipes

Library






Library:

This room is very warm, because of the very hot radiator and the uninsulated pipework is the main cause.

Energy Audit – Future Plans

Energy Audit Identified – Uninsulated Pipework





Future plans

This school wants to tackle uninsulated pipework and the energy audit identified that 4ED: the radiator is hot and the uninsulated heating pipes are thick and travelling around the room leaking heat in to the room. At 25oC it is overheating this room, a good 7oC above the guidelines.

Message

Use your energy audits we did!

